

# Final Reclamation and Stormwater Inspection

June 27, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 302275

Well Name: ALE W #29-21

Inspection Document #: 718600716

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: ALE W #29-21  
Location ID: 302275



**Photo 1.** Looking south across the tank battery location. Desirable perennial vegetation is present on the tank battery and appears to be approaching 80% coverage of the reference area. Undesirable weed kochia is present on the tank battery location.



**Photo 2.** looking north from the midpoint of the tank battery location. See photo 1 comments.



Inspection Photos  
Location Name: ALE W #29-21  
Location ID: 302275



**Photo 3.** looking northwest across the north part of the tank battery. Two meter sheds/ risers.



**Photo 4.** Looking west from wellbore. Well is located on an equipment/ hay storage yard.



Inspection Photos  
Location Name: ALE W #29-21  
Location ID: 302275



**Photo 5.** Looking south from wellbore. See photo 4 comments.



**Photo 6.** Looking east from wellbore. See photo 4 comments.



Inspection Photos  
Location Name: ALE W #29-21  
Location ID: 302275



**Photo 7.** Looking north from wellbore. See photo 4 comments.

Inspection Photos  
Location Name: ALE W #29-21  
Location ID: 302275



**Photo 8.** Google earth aerial imagery taken 09/2020. Meter sheds associated with this well and tank battery location (red circle).