

Closure Checklist

Closure Type: Active Release

Site Name: Pluss L 11-2D

Remediation #::

Latitude, Longitude:: 40.242870, -104.748620

General Condition of Site: Good

USCS Soil Type: SW - Clean Sands - well graded

Estimated Depth of Groundwater **more than 20' bgs**

Hydrocarbon Impacted Soils/Spills **Yes**

Salt Crusted Soils or Impacted Vegetation **None Observed**

Soil Samples

#	Date	Time	Sample ID	PID	Visual	Olfactory	Equipment	Lab
1	06/23/2025	14:45 PM	IWC-01@3"	205	Strong Staining	Strong odor	Wellhead	Yes
2	06/23/2025	14:55 PM	IWC-02@3"	416	Strong Staining	Strong odor	Wellhead	Yes
3	06/23/2025	15:05 PM	IWC-03@3"	522	Strong Staining	Strong odor	Wellhead	Yes

1 - P1



IMG_0258.jpeg

2 - P1



IMG_0259.jpeg



IMG_0260.jpeg

Was impacted soil identified?: Yes

Total number of soil samples field screened: 3

Total number of soil samples collected: 3

Highest PID reading: 522

Total number of soil samples submitted for analysis: 3

Was groundwater encountered during the investigation **No**

Measured Depth to Groundwater:

Was remedial groundwater removal conducted?

Date groundwater was encountered:

Commencement date of removal:

Seen on groundwater?

Free product observed?

Volume of groundwater removed prior to sampling:

Volume of groundwater removed post

sampling:

**Total volume of
groundwater
removed:**

**Total volume of
groundwater
samples collected:**

**Total volume of
groundwater
samples submitted
to lab for analysis:**

Signature

A handwritten signature in black ink, consisting of stylized, cursive letters that appear to be 'JS'.