

# Inspection Photos

June 26th, 2025

Operator: BP America Production

Location ID: 333610

Inspection Document #: 714002246

La Plata County, CO

Township: NWNW 35 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

June 26, 2025  
10° N



**Photo 1.** View of the project area taken from the southern edge facing center.

Inspection Photos  
Location Name: Briggs A1  
Location ID: 333610



**Photo 2.** Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Briggs A1  
Location ID: 333610



**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: location vegetation has met final reclamation standards and appears consistent with adjacent reference areas.

Inspection Photos  
Location Name: Briggs A1  
Location ID: 333610



June 26, 2025  
307° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Stormwater issues on the northern edge of the pad have been addressed.

API #: 067-05000

Inspection Photos  
Location Name: Briggs A1  
Location ID: 333610

June 26, 2025  
328° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Juniper, Gambel Oak, Sagebrush and Indian Ricegrass.

API #: 067-05000