

# Inspection Photos

June 26th, 2025

Operator: BP America Production

Location ID: 325407

Inspection Document #: 714002248

La Plata County, CO

Township: NWNE 8 32N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: WIRT D 1E  
Location ID: 325407

June 26, 2025  
12° N



**Photo 1.** View of the project area taken from the southern edge facing center.

Inspection Photos  
Location Name: WIRT D 1E  
Location ID: 325407



**Photo 2.** Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: WIRT D 1E  
Location ID: 325407



**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: it appears operator has performed mowing and reseeded efforts at the project area.

Inspection Photos  
Location Name: WIRT D 1E  
Location ID: 325407

June 26, 2025  
339° N



**Photo 4.** View of access road which has been mowed and seeded.



Inspection Photos  
Location Name: WIRT D 1E  
Location ID: 325407

June 26, 2025  
209° SW

