

Inspection Photos

June 30th, 2025

Operator: Kinder Morgan

Location ID: 313490

Inspection Document #: 714002264

Montezuma County, CO

Township: SWSW 23 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McElmo Dome Unit YB 2
Location ID: 313490



Photo 1. View of the well pad taken from the access road facing center.

Inspection Photos

Location Name: McElmo Dome Unit YB 2

Location ID: 313490

June 30, 2025
61° NE



Photo 2. View of eastern interim reclamation area.

Inspection Photos

Location Name: McElmo Dome Unit YB 2

Location ID: 313490



June 30, 2025
256° W

Photo 3. View of western interim reclamation area which was recently seeded.