

# Final Reclamation Inspection

June 12, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 330385

Inspection Document #: 718800450

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-FOSTER #3-35  
Location ID: 330385



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows from seeding, but vegetation establishment does not meet Rule 1004 standards. The site is dominated by weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: HSR-FOSTER #3-35  
Location ID: 330385



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-FOSTER #3-35  
Location ID: 330385



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 6.** Photo taken of the access road, from the well location, facing West. Photo illustrates that final reclamation has taken place, but the location is dominated by weedy annual vegetation, including cheatgrass.

Inspection Photos  
Location Name: HSR-FOSTER #3-35  
Location ID: 330385



**Photo 7.** Photo taken of reference area to the well location, north of the location, facing West. Photo illustrates sand sagebrush (*Artemisia filifolia*), with some weedy annual vegetation, including cheatgrass (*Bromus tectorum*).

