

# Final Reclamation Inspection

June 12, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 489425

Inspection Document #: 718800464

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Moser H 26-13,14,24 3N65W Tank Battery

Location ID: 489425



**Photo 1.** Photo taken of the tank battery location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



**Photo 2.** Photo taken of the tank battery location, facing Northwest. See comments under Photo 1.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 718800464



## Inspection Photos

Location Name: Moser H 26-13,14,24 3N65W Tank Battery

Location ID: 489425



**Photo 3.** Photo taken of the tank battery location, facing Northeast. See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing West. See comments under Photo 1.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 718800464



## Inspection Photos

Location Name: Moser H 26-13,14,24 3N65W Tank Battery

Location ID: 489425



**Photo 5.** Photo taken of ground cover at the tank battery location. Photo illustrates bare ground with weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*).



**Photo 6.** Photo taken from the tank battery location, facing west toward the access road to the location. Photo illustrates final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards as the access road is dominated by weedy annual vegetation.





## Inspection Photos

Location Name: Moser H 26-13,14,24 3N65W Tank Battery

Location ID: 489425



**Photo 7.** Photo taken of the reference area to the tank battery location, located north of the location, facing North. Photo illustrates weedy annual vegetation, sand sagebrush (*Artemisia filifolia*), and perennial grass.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 718800464