


Inspection Photos
Location Name: Brown 44-28
API Number: 125-09601



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Brown 44-28
API Number: 125-09601



3. View of equipment inside well house.



4. View of Domestic Tap at well location.

Inspection Photos
Location Name: Brown 44-28
API Number: 125-09601



5. Well location overview.



6. Gas meter inside meter shed

Inspection Photos
Location Name: Brown 44-28
API Number: 125-09601



7. Flow line riser with valve missing plug outside fencing at remote gathering location.



8. Gathering location overview.