

WELL NAME: CENTAUR 24-36, API #: 071-08349, INSP. # 716301200



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: UNUSED EQUIPMENT (PUMPJACK AND ALL ITS COMPONENTS INCLUDING CEMENT PAD). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 7-14-2025.





PHOTO 5: UNUSED EQUIPMENT (PUMPJACK AND ALL ITS COMPONENTS INCLUDING CEMENT PAD). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 7-14-2025.





PHOTO 6: AREA OF IMPACTED SOIL NEAR WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 7-14-2025.





PHOTO 7: OILY WASTE IN PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 OURS TO DRAIL OILY WASTE. CA DATE 7-14-2025.

