

Inspection Photos

Location Name: CECIL USX A-66N64W/1SWSW

Location #: 302411



Photo #1

Cecil USX A 01-13 (123-29088) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 150 yds.



Photo #2

Cecil USX A 01-13, 01-14 Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (2-Wells)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources