

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: ERIE CHAMPLIN 1N68W18NENE

Loc ID: 335769

Inspection: 718600688



Exhibit A



Exhibit B

CA: This location does not meet final reclamation requirements. Undesirable weed kochia is dominant throughout the location. Some desirable vegetation is present, but large areas of the location have little to no desirable vegetation establishment. It appears the access road was preexisting to oil and gas development. See attached pictures. Conduct additional reclamation on location according to Rule 1004. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has addressed the areas with undesirable vegetation, which have been mowed to allow interseeding without disturbing the entire location/established grasses in order to comply with Rule 1004.

