

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 9914 From entrance to location




Photo # 9915 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 9916 Location



Photo # 9917 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 9918 Location



Photo # 9919 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004




Photo # 9920 PRV vent line on separator does not comply with CECMC pressure safety device rules



Photo # 9921 PRV vent line on separator does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC DODGE 8-12 (L8E) Pad

Location #: 324004



Photo # 9922 Weeds in secondary containment



Photo # 9923 Weeds in secondary containment