

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403974939

Receive Date:

03/29/2025

Report taken by:

Krystal Heibel

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

## OPERATOR INFORMATION

Name of Operator: CITATION OIL & GAS CORP	Operator No: 17180	Phone Numbers
Address: 14077 CUTTEN RD		Phone: (281) 891.1550
City: HOUSTON	State: TX	Zip: 77069
Contact Person: Bob Redweik	Email: bredweik@cogc.com	Mobile: (713) 702-7534

## PROJECT, PURPOSE &amp; SITE INFORMATION

## PROJECT INFORMATION

Remediation Project #: 32403 Initial Form 27 Document #: 403564174

## PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☒ Other: Plug and abandon well

## SITE INFORMATION

Yes Multiple Facilities

Facility Type: WELL	Facility ID:	API #: 075-09344	County Name: LOGAN
Facility Name: DUBOIS 6	Latitude: 40.772744	Longitude: -103.217453	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NWNE	Sec: 7	Twp: 9N	Range: 52W
Meridian: 6	Sensitive Area? Yes		

  

Facility Type: LOCATION	Facility ID: 312323	API #:	County Name: LOGAN
Facility Name: DUBOIS-69N52W 7NWNE	Latitude: 40.772667	Longitude: -103.217506	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NWNE	Sec: 7	Twp: 9N	Range: 52W
Meridian: 6	Sensitive Area? Yes		

## SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

### **Other Potential Receptors within 1/4 mile**

Surface water is present in the form of the North Sterling Outlet Canal Riverine Habitat 550 ft south of site which wraps around the site to 1,000 ft east of site. 2 FWS wetlands classified as freshwater ponds are located 800 ft NW of site. The Northwater sterling laterals 8 - 10 branch south off of the Outlet Canal to the SE of the location. 4 wells are present within a 1/2-mile radius of the site, with the closest well being a domestic stock well approximately 1,000 ft N-NW of the site. Static WL in this well is 60 ft bgs. The nearest livestock and occupied buildings are 1,080 ft N-NW of the site. The location falls within the Mule Deer Severe Winter Range and the next nearest CPW HPH's are Aquatic Native Species Conservation Waters located 0.55 mi E & 0.72 mi W of the location.

**DENIED**

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

- ☒ E&P Waste      ☐ Other E&P Waste      ☐ Non-E&P Waste
- ☒ Produced Water      ☐ Workover Fluids
- ☒ Oil      ☐ Tank Bottoms
- ☐ Condensate      ☐ Pigging Waste
- ☐ Drilling Fluids      ☐ Rig Wash
- ☐ Drill Cuttings      ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	N/A	N/A

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

This form serves as notification for the decommissioning of the Dubois #6 wellhead. The ground and subsurface shall be inspected for hydrocarbon impacts during equipment removal. At a minimum, soil sampling shall be conducted in the proposed locations discussed below and shown on the attached proposed soil sample location map.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

One (1) grab soil sample will be collected as described in the shown proposed sample location diagram. Four (4) field screening surface soil samples shall be collected in each cardinal direction surrounding the wellhead and one (1) background sample will be collected from an adjacent, upgradient location. The grab sample will be utilized for full Table 915-1 listed constituents. The background sample will be analyzed for EC, SAR, pH, Boron, and metals.

#### Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Should groundwater be encountered, a sample will be collected as soon as practical and shall be submitted for laboratory analysis of Table 915-1 Inorganic Parameters and Organic Compounds in Groundwater.

#### Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Soil on location will be field screened with PID and EC probe.

## SITE INVESTIGATION REPORT

### SAMPLE SUMMARY

#### Soil

Number of soil samples collected 2

Number of soil samples exceeding 915-1 2

Was the areal and vertical extent of soil contamination delineated? No

#### NA / ND

NA Highest concentration of TPH (mg/kg)

-- Highest concentration of SAR 0.688

BTEX > 915-1 No

Approximate areal extent (square feet) 100

Vertical Extent > 915-1 (in feet) 5

#### Groundwater

Number of groundwater samples collected 0

Highest concentration of Benzene (µg/l)

Was extent of groundwater contaminated delineated? No

Highest concentration of Toluene (µg/l)

Depth to groundwater (below ground surface, in feet)

Highest concentration of Ethylbenzene (µg/l)

Number of groundwater monitoring wells installed

Highest concentration of Xylene (µg/l)

Number of groundwater samples exceeding 915-1

Highest concentration of Methane (mg/l)

#### Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

### OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

### REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

### SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Citation has determined this is legacy contamination and not an active leak.

### REMEDIAL SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

On 6/24/2024, one (1) soil sample and one (1) background sample were collected and analyzed. SS01 was found to have elevated levels of hydrocarbons, arsenic, and pH above Table 915 limits. BKG01 was found to have elevated levels of arsenic and pH above Table 915 limits. Remediation activities for substantial impacts will involve the excavation of impaired soils for transport to an approved disposal facility. Following excavation and removal of any impacted soils, confirmation sampling will be conducted to confirm successful remediation. Excavated areas will then be backfilled with clean soil as necessary and seeding of the remediated area to re-establish a proper seedbed will be conducted.

### Soil Remediation Summary

☐ In Situ

☐ Ex Situ

Bioremediation ( or enhanced bioremediation )

Excavate and offsite disposal

Chemical oxidation

If Yes: Estimated Volume (Cubic Yards)

Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or ECMC Facility ID #

Natural Attenuation

Excavate and onsite remediation

Other

Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

#### ☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Citation carries general liability insurance of \$2,000,000, with excess liability insurance of \$35,000,000. Citation also carries pollution/waste liability insurance of \$20,000,000, and environmental related liability insurance of \$3,000,000 for all active wells and \$1,000,000 for all plugged and abandoned wells. Citation maintains \$1,135,000 in surety bonds with the ECMC. There is no site-specific financial assurance associated with this remediation project. Citation does not intend to file an insurance claim for this remediation project.

Operator anticipates the remaining cost for this project to be: \$ 10000

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?



Does Groundwater meet Table 915-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following wellhead removal activities, the location was backfilled, compacted, and re-contoured to match pre-existing conditions. The location will be reclaimed in accordance with ECMC 1000 series.

Is the described reclamation complete? No \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 10/01/2023

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 11/20/2023

Proposed site investigation commencement. 11/20/2023

Proposed completion of site investigation. 05/30/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 07/01/2025

Proposed date of completion of Remediation. \_\_\_\_\_

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

## OPERATOR COMMENT

This is the 1Q2025 quarterly update for this location. Due to local resource limitations and the need to address higher priority sites, Citation was unable to keep up with quarterly progress for this project. Moving forward, Citation has addressed the situation and will continue with quarterly reporting as required by the ECMC to progress this project. During 4Q2024, the location was inspected to document the status and further evaluate a plan of action. Citation is currently developing this plan and will be increasing remediation efforts for 2025 by retaining additional third-party contractor support starting 2Q2025.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Joel Mason

Title: Agent

Submit Date: 03/29/2025

Email: joel.mason@absarokasolutions.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:

Date:

Remediation Project Number: 32403

## COA Type

## Description

0 COA	
-------	--

## ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

## Att Doc Num

## Name

403974939	FORM 27 DENIED
404135786	ANALYTICAL RESULTS
404135787	ANALYTICAL RESULTS
404135789	PHOTO DOCUMENTATION
404135791	SOIL SAMPLE LOCATION MAP
404272317	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 6 Files

## General Comments

## User Group

## Comment

## Comment Date

Environmental	This form is denied because one or more of the attached laboratory analytical reports is not secured. ECMC has not reviewed this form or any other attachments on this Form. Operator shall resubmit the Form 27 and ensure all laboratory reports are secured and contain metadata appropriate to document any differences in created and modified dates, and/or the laboratory analytical report shall be signed with a validated signature certificate.	07/09/2025
---------------	--	------------

Total: 1 comment(s)