

# Final Reclamation Inspection

June 17, 2025

Operator: PADCO LLC - 24500

Location ID: 317036

Inspection Document #: 718800471

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FASSLER #3  
Location ID: 317036



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that no final reclamation activities have taken place, per the approved variance request, and gravel remains on location.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: FASSLER #3  
Location ID: 317036



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: FASSLER #3  
Location ID: 317036



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation was observed at the location, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 6.** Photo taken of the access road, facing south towards the well location. Photo illustrates that final reclamation has not taken place along the access road.



Inspection Photos  
Location Name: FASSLER #3  
Location ID: 317036



**Photo 7.** Photo taken of the access road, facing north away from the well location. See comments under Photo 6.

