

# Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328320

Inspection Document #: 718800480

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CANNON #H 35-12  
Location ID: 328320



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding. However, vegetation has not established to Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: CANNON #H 35-12  
Location ID: 328320



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.





Inspection Photos  
Location Name: CANNON #H 35-12  
Location ID: 328320



**Photo 5.** Photo taken of the access road to the well location, facing North towards the location. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



**Photo 6.** Photo taken of ground cover at the well location. Photo illustrates bare ground and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.





Inspection Photos  
Location Name: CANNON #H 35-12  
Location ID: 328320



**Photo 7.** Photo taken of the reference area, located east of the well location, facing northeast. Photo illustrates annual vegetation including prairie sunflower (*Helianthus petiolaris*).

