

# Inspection Photos

July 7th, 2025

Operator: Kinder Morgan

Location ID: 313533

Inspection Document #: 714002277

Montezuma County, CO

Township: NWSW 31 37N 17W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McElmo Dome Unit MC #4

Location ID: 313533

July 7, 2025  
16° N



**Photo 1.** View of project area taken from the southern edge facing center.

Inspection Photos

Location Name: McElmo Dome Unit MC #4

Location ID: 313533



**Photo 2.** Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos

Location Name: McElmo Dome Unit MC #4

Location ID: 313533



**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: location was recently reclaimed and seeded. Evidence of germinated species observed at both the well pad and access road.

Inspection Photos

Location Name: McElmo Dome Unit MC #4

Location ID: 313533



July 7, 2025  
334° NW



**Photo 4.** View of access road facing the project area.

Inspection Photos

Location Name: McElmo Dome Unit MC #4

Location ID: 313533



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Rabbit Brush and Crested Wheatgrass.

API #: 083-06437