

Final Reclamation and Stormwater Inspection

July 2, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 422522

Well Name: Miller/X31-04 TANK

Inspection Document #: 718600734

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Miller/X31-04 TANK
Location ID: 422522



Photo 1. Picture taken near the southern entrance to the former tank battery looking northeast. A patch of bare soil is present with less vegetation than the surrounding area.



Photo 2. Looking north from the center of the tank battery location. The tank battery location is fenced out of the surrounding area. No oil and gas equipment remains on location. Desirable vegetation has established on the location.



Inspection Photos
Location Name: Miller/X31-04 TANK
Location ID: 422522



Photo 3. Looking west from the center of the location. See photo 2 comments.



Photo 4. Looking south from the center of the location. See photo 2 comments.



Inspection Photos
Location Name: Miller/X31-04 TANK
Location ID: 422522




Photo 5. Looking east from the center of the location. See photo 2 comments.



Photo 6. Looking southwest across the location. See photo 2 comments.

