

Inspection Photos

Loc: 309049

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 7/10/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing northwest along the access road.



Inspection Photos



Photo 2. Facing south toward the wellsite location.



Inspection Photos



Photo 3. Facing toward the cut which is stabilized with vegetation.



Inspection Photos



Photo 4. Facing toward the wellhead.

