

Inspection Photos

Loc: 309451

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 7/10/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the recontoured access road.



Inspection Photos



Photo 2. Facing southwest toward the location. It appears perennial vegetation has reestablished to reference area levels.



Inspection Photos



Photo 3. Bottom side of the location facing north. There are some noxious weeds in this area that need to be controlled.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309451 | Date: 7/10/2025

Inspection Photos



Photo 4. center of the location facing south. There are some Canada thistle shown at red arrow.



Inspection Photos



Photo 5. Facing toward the southeast corner of the location. There are noxious weeds in this area that need to be controlled. Red arrow points to Bull thistle and Canada thistle.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309451 | Date: 7/10/2025

Inspection Photos



Photo 6. Center of the location facing east. There is a suing Musk thistle plant that should be bagged and removed.



Inspection Photos



Photo 7. Facing east from the top side of the location. There are noxious along this upper slope shown at red arrow. (Canada thistle, Mullein)



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309451 | Date: 7/10/2025