

# Inspection Photos

Loc: 309035

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 7/10/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest the along the main access road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309035 | Date: 7/10/2025

## Inspection Photos



**Photo 2.** Facing southwest toward the wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309035 | Date: 7/10/2025

## Inspection Photos



**Photo 3.** Facing west at the north side of the location. This area appears to have been reseeded but has not established perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309035 | Date: 7/10/2025

## Inspection Photos



**Photo 4.** Facing south toward the fill slope. Areas of the fill slope have not adequately established perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309035 | Date: 7/10/2025


## Inspection Photos



**Photo 5.** Facing west along the fill slope. This area appears to have been reseeded but has not established vegetation.



## Inspection Photos



**Photo 6.** South side of the location facing north.

