

Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 418287

Inspection Document #: 718800497

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON X #02-28
Location ID: 418287



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding. However, vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: CANNON X #02-28
Location ID: 418287



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CANNON X #02-28
Location ID: 418287



Photo 5. Photo taken of the access road to the well location, facing East. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 6. Photo taken of the access road, facing southwest. See comments under Photo 5.

Inspection Photos
Location Name: CANNON X #02-28
Location ID: 418287



Photo 7. Photo taken of the access road to the well location, facing east. Photo illustrates stormwater erosion along the access road.



Photo 8. Photo taken of the access road. Photo illustrates stormwater erosion.



Inspection Photos
Location Name: CANNON X #02-28
Location ID: 418287



Photo 9. Photo taken from the entrance to the well location, facing west. Photo illustrates fencing remains in place, but is in disrepair.



Photo 10. Photo taken from the southern perimeter to the well location, facing west. Photo illustrates weed debris in the form of russian thistle (*Salsola tragus*) was observed in the fence line.



Inspection Photos
Location Name: CANNON X #02-28
Location ID: 418287



Photo 11. Photo taken of the reference area, located west of the well location, facing north. Photo illustrates that the location is dominated by sand sagebrush (*Artemisia filifolia*).

