

Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 420050

Inspection Document #: 718800507

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DECHANT STATE H #36-18D
Location ID: 420050



Photo 1. Photo taken from the multi-well location, facing North. Photo illustrates final reclamation activities have taken place, with evidence of straw mulch, but vegetation has not established to Rule 1004 standards at the location.



Photo 2. Photo taken from the multi-well location, facing East. See comments under Photo 1.

Inspection Photos

Location Name: DECHANT STATE H #36-18D

Location ID: 420050



Photo 3. Photo taken from the multi-well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the multi-well location, facing West. See comments under Photo 1.



Inspection Photos

Location Name: DECHANT STATE H #36-18D

Location ID: 420050



Photo 5. Photo taken of the multi-well location, facing North. Photo illustrates that vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken of the reference area, located south of the location, facing south. Photo illustrates perennial grass vegetation.

