

Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328482

Inspection Document #: 718800509

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SPIKE STATE GWS #H 36-04

Location ID: 328482



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards as patches of bare ground remain.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos

Location Name: SPIKE STATE GWS #H 36-04

Location ID: 328482



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos

Location Name: SPIKE STATE GWS #H 36-04

Location ID: 328482



Photo 5. Photo taken of the location. Photo illustrates that final reclamation activities have taken place, but patches of bare ground remain at the location.



Photo 6. Photo taken of the reference area for the well location, located south of the location, facing south. Photo illustrates perennial grass vegetation.

