

# Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 420221

Inspection Document #: 718800515

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DECHANT/H36-24 TANK  
Location ID: 420221



**Photo 1.** Photo taken from the tank battery location, facing southeast. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Bare ground and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, were observed across the location.



**Photo 2.** Photo taken from the tank battery location, facing north. See comments under Photo 1.

Inspection Photos  
Location Name: DECHANT/H36-24 TANK  
Location ID: 420221



**Photo 3.** Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



**Photo 4.** Photo taken of ground cover at the tank battery location. Photo illustrates patches of bare ground and weedy annual vegetation.

Inspection Photos  
Location Name: DECHANT/H36-24 TANK  
Location ID: 420221



**Photo 5.** Photo taken of ground cover at the tank battery location. Photo illustrates cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, which was observed across the location.



**Photo 6.** Photo taken of the reference area to the tank battery location, located south of the location, facing east. Photo illustrates rye cropland.