

Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 420219

Inspection Document #: 718800520

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DECHANT STATE #H36-11
Location ID: 420219



Photo 1. Photo taken from the multi-well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. The location is adjacent to an access road.



Photo 2. Photo taken from the multi-well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DECHANT STATE #H36-11
Location ID: 420219



Photo 3. Photo taken from the multi-well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the multi-well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: DECHANT STATE #H36-11
Location ID: 420219



Photo 5. Photo taken of the multi-well location, facing northwest. Photo illustrates the location is adjacent to an access road in use by the landowner. Final reclamation does not meet Rule 1004 standards as bare ground remains at the well location along the northeastern portion of the access road.



Photo 6. Photo taken of the reference area for the well location, southeast of the location, facing southeast. Photo illustrates annual vegetation adjacent to the access road and rye cropland.

