

# Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 317694

Inspection Document #: 718800524

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DECHANT #H36-24  
Location ID: 317694



**Photo 1.** Photo taken from the multi-well location, from well API# 123-07590 (SPIKE STATE GWS H #36-11J), facing North. Photo illustrates that final reclamation activities have taken place, but weedy annual vegetation, including cheatgrass (*Bromus tectorum*), was observed across the location.



**Photo 2.** Photo taken from the multi-well location, from well API# 123-07590 (SPIKE STATE GWS H #36-11J), facing East. See comments under Photo 1.





Inspection Photos  
Location Name: DECHANT #H36-24  
Location ID: 317694



**Photo 3.** Photo taken from the multi-well location, from well API# 123-07590 (SPIKE STATE GWS H #36-11J), facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the multi-well location, from well API# 123-07590 (SPIKE STATE GWS H #36-11J), facing West. See comments under Photo 1.





Inspection Photos  
Location Name: DECHANT #H36-24  
Location ID: 317694



**Photo 5.** Photo taken from the multi-well location, from well API# 123-35254 (DECHANT STATE #H36-33D), facing North. See comments under Photo 1.



**Photo 6.** Photo taken from the multi-well location, from well API# 123-35254 (DECHANT STATE #H36-33D), facing East. See comments under Photo 1.





Inspection Photos  
Location Name: DECHANT #H36-24  
Location ID: 317694



**Photo 7.** Photo taken from the multi-well location, from well API# 123-35254 (DECHANT STATE #H36-33D), facing South. See comments under Photo 1.



**Photo 8.** Photo taken from the multi-well location, from well API# 123-35254 (DECHANT STATE #H36-33D), facing West. See comments under Photo 1.



Inspection Photos  
Location Name: DECHANT #H36-24  
Location ID: 317694



**Photo 9.** Photo taken of ground cover at the location. Photo illustrates cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 10.** Photo taken of the access road to the well location. Photo illustrates final reclamation activities have taken place, but weedy annual vegetation, including cheatgrass (*Bromus tectorum*), was observed across the location.





Inspection Photos  
Location Name: DECHANT #H36-24  
Location ID: 317694



**Photo 11.** Photo taken of the reference area to the multi-well location, west of the location, facing north. Photo illustrates rye cropland.