

Inspection Photos

Operator: **KT RESOURCES LLC - 10775**

Location Name: **WRD UNIT #29-33 WDW**

Location ID: **336394** API #: **05-103-10113**

Inspection Date: **7/11/2025** Inspection Doc#: **693808854**



Injection wellhead



Pump housing

Inspection Photos

Operator: **KT RESOURCES LLC - 10775**

Location Name: **WRD UNIT #29-33 WDW**

Location ID: **336394** API #: **05-103-10113**

Inspection Date: **7/11/2025** Inspection Doc#: **693808854**



Tank Battery



Combustor

Inspection Photos

Operator: **KT RESOURCES LLC - 10775**

Location Name: **WRD UNIT #29-33 WDW**

Location ID: **336394** API #: **05-103-10113**

Inspection Date: **7/11/2025** Inspection Doc#: **693808854**



Pump jack



Tank battery

Inspection Photos

Operator: **KT RESOURCES LLC - 10775**

Location Name: **WRD UNIT #29-33 WDW**

Location ID: **336394** API #: **05-103-10113**

Inspection Date: **7/11/2025** Inspection Doc#: **693808854**



Separator and meter housing