

Inspection Photos

Operator: ANSCHUTZ EXPLORATION CORP. - 3104

Location Name: PRF C-1W

Location ID: 315979 API #: 05-103-09519

Inspection Date: 7/11/2025 Inspection Doc#: 693808856



Injection wellhead housing



Pump housing

Inspection Photos

Operator: ANSCHUTZ EXPLORATION CORP. - 3104

Location Name: PRF C-1W

Location ID: 315979 API #: 05-103-09519

Inspection Date: 7/11/2025 Inspection Doc#: 693808856



Tank battery



Location entrance