

# Inspection/Audit Photos


Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Jul 10, 2025 at 10:07:26 AM  
+39.669822,-108.796533 ±9.24m



Jul 10, 2025 at 10:21:37 AM  
+39.669679,-108.796289 ±8.50m

Photo # 9419 Entrance to location

Photo # 9431 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9420 Location



Photo # 9424 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9489 NW corner of location



Photo # 9490 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9491 SE corner of location



Photo # 9492 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9422 Wellhead sign lacks required information/not in compliance with CECMC rules



Photo # 9432 No battery signage/not in compliance with CECMC rules

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



**Photo # 9443 Unused flowline does not comply with CECMC 600 & 1100 series rules**



**Photo # 9445 Unused flowline does not comply with CECMC 600 & 1100 series rules**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



**Photo # 9446 Unused flowline does not comply with CECMC 600 & 1100 series rules**

**Photo # 9452 Meter house open to wildlife/available for entry by wildlife**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



**Photo # 9458 Multiple holes in separator building open to wildlife/available for entry by wildlife**



**Photo # 9462 Debris on location**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9463 Debris on location



Photo # 9466 Debris on location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9471 Debris on location



Photo # 9473 Debris on location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9478 Debris on location



Photo # 9481 Debris on location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9484 Debris on location



Photo # 9487 Debris on location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 07/10/2025



Photo # 9488 Debris on location