

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD


Location ID: 335758

Date: 07/10/2025



Jul 10, 2025 at 12:58:39 PM  
+39.659106,-108.804369 ±2.82m

Photo # 9517 Entrance to location



Jul 10, 2025 at 1:15:52 PM  
+39.658623,-108.804383 ±9.36m

Photo # 9533 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



Photo # 9518 Location



Photo # 9525 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



Photo # 9568 SE corner of location



Photo # 9569 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



Photo # 9570 NW corner of location



Photo # 9572 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



Photo # 9519 Wellhead sign lacks required information/not in compliance with CECMC rules



Photo # 9539 No battery signage/not in compliance with CECMC rules

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



**Photo # 9545 Hole in separator building open to wildlife/available for entry by wildlife**

**Photo # 9546 Hole in separator building open to wildlife/available for entry by wildlife**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



**Photo # 9547 Suspected leaks on production tank/tank appears to lack integrity**



**Photo # 9549 Suspected leaks on production tank/tank appears to lack integrity**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



**Photo # 9551 Suspected leaks on production tank/tank appears to lack integrity**



**Photo # 9552 Suspected leaks on production tank/tank appears to lack integrity**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



Photo # 9563 Debris on location



Photo # 9564 Debris on location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7412 PAD

Location ID: 335758

Date: 07/10/2025



Photo # 9566 Debris on location