

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9590 Entrance to location



Photo # 9602 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9642 NW corner of location



Photo # 9643 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9644 SE corner of location



Photo # 9645 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9594 Wellhead sign lacks required information/not in compliance with CECMC rules



Photo # 9631 Hole in meter house open to wildlife/available for entry by wildlife

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9634 Hole in meter house open to wildlife/available for entry by wildlife



Photo # 9637 Debris on location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9638 Debris on location



Photo # 9640 Debris on location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7426 PAD

Location ID: 316286

Date: 07/11/2025



Photo # 9641 Debris on location