

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1402 From entrance to location



Photo # 1403 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256




Photo # 1404 Location



Photo # 1405 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1406 Location



Photo # 1407 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1408 Location



Photo # 1409 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1410 Location

Photo # 1411 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1412 Location



Photo # 1413 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1414 Location



Photo # 1415 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1416 Location



Photo # 1417 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1418 Location



Photo # 1419 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1420 Location



Photo # 1421 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 1422 Location



Photo # 1423 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7129 From inspection/audit 708906125 conducted on 03/25/2025 PRV vent lines do not comply with CECMC pressure safety device rules

Photo # 1424 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256




Photo # 7131 From inspection/audit 708906125 conducted on 03/25/2025 PRV vent lines do not comply with CECMC pressure safety device rules



Photo # 1425 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7132 From inspection/audit 708906125 conducted on 03/25/2025 Tank battery lacks required signage



Photo # 1426 Tank battery lacks required signage