

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404137695

Receive Date:

06/10/2025

Report taken by:

Collin Metz

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers
Address: P O BOX 173779		Phone: (970) 515-1110
City: DENVER	State: CO	Zip: 80217-3779
Contact Person: Macy Kiel	Email: DJRemediation_Forms@oxy.com	Mobile: ()

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 29438 Initial Form 27 Document #: 403379355

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-38234	County Name: WELD
Facility Name: HOWARD 9C-22HZ	Latitude: 40.017137	Longitude: -104.870463	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SESE	Sec: 27	Twp: 1N	Range: 67W Meridian: 6 Sensitive Area? Yes

Facility Type: SPILL OR RELEASE	Facility ID: 483525	API #: _____	County Name: WELD
Facility Name: Howard 9C-22 Wellhead	Latitude: 40.017137	Longitude: -104.870463	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SESE	Sec: 27	Twp: 1N	Range: 67W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications CL

Most Sensitive Adjacent Land Use residential

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Domestic water well: approximately 410' E and 1240' E
Surface water: none
Wetlands: none
Spring: none
Livestock: none
Occupied Building: multiple occupied buildings within 1/4 mile
High Priority Habitats: none

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	TBD	Groundwater samples/laboratory analytical results
Yes	SOILS	16' (E-W) x 18' (N-S) x 10' bgs	inspection/soil samples/laboratory analytical results

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On December 20, 2022, a bushing seal failure on the stuffing box caused a release of an unknown volume of hydrocarbons at the Howard 9C-22 wellhead location. The ECMC issued Spill/Release Point ID 483525 for this release. On December 20, 2022, an initial waste characterization soil sample (Initial Waste Characterization@2.5') was collected from the material most likely to be impacted, based on field observations and proximity to the release location at the wellhead, and submitted for laboratory analysis of the full ECMC Table 915-1 analytical suite. Laboratory analytical results for soil sample Initial Waste Characterization@2.5' indicated that the benzene, toluene, naphthalene, 1,2,4-trimethylbenzene (TMB), 1,3,5-TMB, 1-methylnaphthalene, 2-methylnaphthalene, arsenic, barium, and selenium concentrations exceeded the applicable ECMC Table 915-1 standards. Groundwater was not encountered during excavation activities. Soil sample location and field screening data are presented in Table 1. The excavation soil sample locations are illustrated on Figure 1.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

From December 20, 2022 through January 10, 2023, excavation activities were conducted to address soil impacts around the release location and five (5) confirmation soil samples were collected from the base and sidewalls of the final excavation extent, at depths of approximately 10' and 6' bgs, respectively. Based on waste characterization results (Initial Waste Characterization@2.5'), the confirmation soil samples were submitted for laboratory analysis of benzene, toluene, naphthalene, 1,2,4-TMB, 1,3,5-TMB, 1 and 2 methylnaphthalene, Ar, Ba, and Se using ECMC-approved methods, as previously approved on Form 27-Supplemental Document #403809000. Analytical results indicated that constituent concentrations in the soil samples collected from the final excavation extents exceeded the applicable ECMC Table 915-1 standards. However, due to the proximity of active wellhead surface and subsurface infrastructure in the surrounding area, excavation activities could not safely continue.

Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was not encountered during initial wellhead excavation activities.

If groundwater is encountered during ongoing assessment and remediation activities, a minimum of one grab sample will be collected as soon as practical. Groundwater samples will be submitted to an accredited laboratory for all analytes listed in ECMC Table 915-1 Organic Compounds in Groundwater (benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, 1,2,4-trimethylbenzene (1,2,4 – TMB), and 1,3,5-trimethylbenzene (1,3,5 – TMB)) and Groundwater Inorganic Parameters (total dissolved solids (TDS), chloride, and sulfate) using standard methods appropriate for detecting the target analytes in ECMC Table 915-1.

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 19

Number of soil samples exceeding 915-1 19

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 288

NA / ND

-- Highest concentration of TPH (mg/kg) 148

-- Highest concentration of SAR 2.47

BTEX > 915-1 Yes

Vertical Extent > 915-1 (in feet) 10

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

Site-specific background soil samples will be collected to assess native soil conditions.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Due to the proximity of the wellhead to surrounding surface and subsurface infrastructure, excavation activities could not safely continue. On August 14, 2024, four permanent soil vapor extraction (SVE) remedial wells were installed to approximately 10' below ground surface. Locations of the SVE remedial wells are illustrated on Figure 2. Mobile SVE remedial events will be completed to address remaining soil impacts.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Between December 20, 2023 and January 10, 2023, approximately 38 cubic yards of impacted soil slurry was excavated via hydro excavation and transported to Aggregate State Fluid Recycling Facility in Fort Lupton, Colorado for disposal. Laboratory analytical results indicated that constituent concentrations in the soil samples collected from the final excavation extents exceeded the applicable ECOM Table 915-1 standards. Due to the proximity of the wellhead to surrounding surface and subsurface infrastructure, excavation activities could not safely continue. The excavation area has been backfilled and contoured to match pre-existing conditions.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory analytical results indicated that constituent concentrations in the soil samples collected from the final excavation extents exceeded the applicable ECMC Table 915-1 standards. On August 14, 2024, four permanent SVE remedial wells were installed to approximately 10' below ground surface. During SVE well installation, soil samples were collected at depths of 6' and 10' bgs in the SVE locations. Analytical results from the soil sample indicated that constituent concentrations were within ECMC Table 915-1 standards, with the exception of metal concentrations. Site-specific background samples will be collected to assess native soil conditions. A SVE pilot test was conducted on February 24, 2025. Based on the results of the SVE pilot test, additional site assessment activities will be completed and additional SVE remedial wells may be installed closer to the former excavation area.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

☒ Ex Situ

Yes

_____ Excavate and offsite disposal

_____ If Yes: Estimated Volume (Cubic Yards) 38

_____ Name of Licensed Disposal Facility or ECMC Facility ID # 456644

No

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

KMOG has sufficient insurance and bonding to fully address the anticipated costs of Remediation, including the remaining estimated costs for this project. KMOG currently has over 40 million in bonds with the Energy and Carbon Management Commission. The cost for remediation is a preliminary estimate only, costs may change upwards or downward based on site-specific information. KMOG makes no representation or guarantees as to the accuracy of the preliminary estimate.

Operator anticipates the remaining cost for this project to be: \$ 20000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

NA

Volume of E&P Waste (solid) in cubic yards 38

E&P waste (solid) description impacted soil

ECMC Disposal Facility ID #, if applicable: 456644

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site will be reclaimed in accordance with ECMC 1000 Series Reclamation Rules.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/20/2022

Actual Spill or Release date, or date of discovery. 12/20/2022

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 12/20/2022

Proposed site investigation commencement. 12/20/2022

Proposed completion of site investigation. 12/31/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 12/20/2022

Proposed date of completion of Remediation. 12/31/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Macy Kiel

Title: Environmental Engineer

Submit Date: 06/10/2025

Email: DJRemediation_Forms@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Collin Metz

Date: 07/14/2025

Remediation Project Number: 29438

COA Type**Description**

	Operator submitted this form outside of the approved reporting schedule (Quarterly). In accordance with Rule 913.e.(3), Operator will adopt a quarterly reporting schedule (every 90 days); additional violations may result in enforcement.
1 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

404137695	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
404137696	PHOTO DOCUMENTATION
404137699	MAP
404137700	ANALYTICAL RESULTS
404137701	ANALYTICAL RESULTS
404139427	SOIL SAMPLE LOCATION MAP
404277658	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 7 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)