

Audit Photos

Location Name: QB ENERGY OPERATING LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 7/9/2025



Location Overview – Photo #09652



Location – Photo #09659

Audit Photos

Location Name: QB ENERGY OPERATING LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 7/9/2025



Location – Photo #09655



Location – Photo #09653

Audit Photos

Location Name: QB ENERGY OPERATING LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 7/9/2025



Location – Photo #09654



Location – Photo #09661

Audit Photos

Location Name: QB ENERGY OPERATING LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 7/9/2025



Damaged Wildlife Netting – Photo #09657



Damaged Wildlife Netting – Photo #09658