

Final Reclamation and Stormwater Inspection

July 11, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 320772

Well Name: SIERRA-MURPHY #31-5

Inspection Document #: 718600770

Arapahoe County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SIERRA-MURPHY #31-5
Location ID: 320772



Photo 1. Looking east down the former access road away from the location. Desirable vegetation on the access road appears to be approaching 80% coverage of the reference area.



Photo 2. Looking east from the center of the location. Desirable vegetation is present on location and appears to be approaching 80% coverage of surrounding reference vegetation.

Inspection Photos
Location Name: SIERRA-MURPHY #31-5
Location ID: 320772



Photo 3. Looking north from the center of the location. See photo 2 comments.



Photo 4. Looking west from the center of the location. See photo 2 comments.



Inspection Photos
Location Name: SIERRA-MURPHY #31-5
Location ID: 320772



Photo 5. Picture taken on the east side of the location. A 20'x20' foot pit approximately 3' deep is present around the wellbore. A pipe is exposed on the surface (red arrow).



Photo 6. Looking west across the depression and exposed pipe (red arrow).

Inspection Photos
Location Name: SIERRA-MURPHY #31-5
Location ID: 320772



Photo 7. Picture of the exposed pipe.



Photo 8. Reference vegetation to the south of the location.

Inspection Photos
Location Name: SIERRA-MURPHY #31-5
Location ID: 320772



Photo 9. Google earth imagery taken 09/2013. The exposed pipe appears to be related to oil and gas. Approximate location of pipe (red circle).