

# Inspection Photos

**06/02/2025**

**Operator:** BONANZA CREEK ENERGY OPERATING  
LLC- #8960

**Location ID:** 324583

**Inspection Document #:** 712300134

Jackson County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mccallum Unit # 36 Pad  
Location ID: 324583



**Photo 1.** Photo taken from the entrance to the main access road, facing southwest. Photo illustrates utility equipment remains leading up to, and on the Location.



**Photo 2.** Photo taken from the entrance to the spur access road.

Inspection Photos  
Location Name: Mccallum Unit # 36 Pad  
Location ID: 324583



**Photo 3.** Photos 3-6 taken at the pad center, facing North, East, South and West illustrating the overview of the Location. Photos illustrates vegetation has reached 80% of reference area. Utility equipment remains on Location.



**Photo 4.** See comments under photo 3.



Inspection Photos  
Location Name: Mccallum Unit # 36 Pad  
Location ID: 324583



**Photo 5.** See comments under photo 3.



**Photo 6.** See comments under photo 3.



Inspection Photos  
Location Name: Mccallum Unit # 36 Pad  
Location ID: 324583



**Photo 7.** Photos 7-8 taken of the reference area vegetation west of the location, facing east and southwest. Vegetation is predominantly sagebrush, Phlox, and Indian Ricegrass.



**Photo 8.** See comments under Photo 7.