

# Inspection Photos

**06/03/2025**

**Operator:** KP KAUFFMAN COMPANY INC - #46290

**Location ID:** 324771

**Inspection Document #:** 712300136

Jackson County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mccallum Unit # 5 Pad  
Location ID: 324771



**Photo 1.** Photos 1-4 taken at the pad center, facing North, East, South and West illustrating the overview of the Location.



**Photo 2.** See comments under photo 1.

Inspection Photos  
Location Name: Mccallum Unit # 5 Pad  
Location ID: 324771



**Photo 3.** See comments under photo 1.



**Photo 4.** See comments under photo 1.



Inspection Photos  
Location Name: Mccallum Unit # 5 Pad  
Location ID: 324771



**Photo 5.** Photo illustrates that markers/equipment remain on Location.



**Photo 6.** It appears that gravel was not removed, compaction alleviation has not occurred, and the Location has not been re-seeded.

Inspection Photos  
Location Name: Mccallum Unit # 5 Pad  
Location ID: 324771



**Photo 7.** Photo illustrates that the access road remains with predominantly bare soil.



**Photo 8.** It was observed that undesirable vegetation (Russian Thistle) was growing across the Location.

Inspection Photos  
Location Name: Mccallum Unit # 5 Pad  
Location ID: 324771



**Photo 9.** Photos 9-10 taken of the reference area vegetation northwest of the location, facing northwest and north. Vegetation is predominantly sagebrush and Indian Ricegrass.



**Photo 10.** See comments under Photo 9.