

Inspection Photos

07/10/2025

Operator: LARAMIE ENERGY LLC #10433

Location ID: 312666

Inspection Doc: 718100642

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312666



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312666



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312666



Photo 3: Photo shows cut slopes on the east end of the Location. There are areas of the slopes where perennial vegetative establishment does not appear to be progressing towards 1003 uniform standards- additional seeding efforts are advised



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312666



Photo 4: Photos taken from the interim areas on the west end of the Location. Reclamation is progressing towards 1003 standards within these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312666



Photo 5: Photos taken from the battery facility. Photos show lines at tanks missing cap/plug.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources