

Inspection Photos

Location Name: DYER USX AB/35-68-1HN

Location #: 426749



Photo #1

Dyer USX AB 35-67-1HN (123-34772) Wellsite

Plugged & Abandoned | PA

Red PTA tag; Surface plug date: 05/15/2025

Cut / Cap: Pending



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: DYER USX AB/35-68-1HN

Location #: 426749



Photo #2

Dyer USX AB 35-68-1HN, Dyer USX AB 35-67-1HN

Plugged & Abandoned | PA (2: Wells)

Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



Photo #3

Dyer USX AB 35-68-1HN, Dyer USX AB 35-67-1HN

Plugged & Abandoned | PA (2: Wells)

Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 426749



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources