

WELL NAME: RADISH 44-8, API #: 071-09376, INSP. # 716301220



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: RECLAIMED PRODUCED WATER PIT AREA.



PHOTO 5: VEGITATION IN THE MIDDLE OF LOCATION NOT MAINTAINED. MAINTAIN VEGITATION PER RULE 606. CA DATE 7-25-2025.



WGS84 ±46ft 37.26609, -104.90453 Δ ft ±13ft 8102 \triangle M ±10 SW218



Colorado Oil & Gas Conservation commission
© 14-Jul-25 12:27:38

PHOTO 6: VEGITATION DOWN THE CENTER LINE OF ROW IS NOT MAINTAINED. MAINTAIN VEGITATION PER RULE 606. CA DATE 7-25-2025.



PHOTO 7: AREA OF IMPACTED SOIL NEAR WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 7-25-2025.