

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9759 Entrance to location



Photo # 9772 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9764 Location



Photo # 9795 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9796 SE corner of location



Photo # 9797 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9798 NW corner of location



Photo # 9761 Wellhead sign lacks required information/not in compliance with CECMC rules

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9777 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity



Photo # 9778 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Jul 14, 2025 at 11:08:05 AM
+39.653431,-108.806677 ±6.87m



Jul 14, 2025 at 11:10:24 AM
+39.653431,-108.806677 ±6.87m

Photo # 9779 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity

Photo # 9782 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9784 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity



Photo # 9787 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9788 Multiple holes/tears in secondary containment liner/liner needs maintenance/liner lacks integrity



Photo # 9793 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 07/14/2025



Photo # 9794 Debris