

Work Completion Report

Contractor: US HYDRO

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
HSR-REDMOND 12-21 (2025 Seasonal)	Spring	Josh Green	6/12/2025

Work Summary	Reclamation Type	Land Use
Interseeded the tank battery, access road and well head.	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance		No	Location(s): HSR-REDMOND-63N67W_21NWSW Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
Seed Mix: **Dryland Pasture (15.00 lbs)**
Crop Type:
Soil Type: **Gravel**
Stabilization Date:
Seeding Date: **6/12/2025**
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

PHOTOS

Photo Name: Seed Mix
Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: Interseeding well head

Description:



Photo Name: Interseeding tank battery

Description:



Photo Name: Tank battery after seeding

Description:



Photo Name: Well head after seeding

Description:



Photo Name: Access road after seeding

Description:

