

Operator: AXIS Exploration

Location Name: Sabo 22-19 4 TB

Loc ID: 460776

Inspection: 713602311



Exhibit A



Exhibit B



Exhibit C

CA: The former tank battery location is not reclaimed. There are undesirable weeds and areas that are bare of vegetation. Soils need to be cross ripped to at least 18 inches and decompacted. The location needs to be reseeded to establish a perennial vegetation cover that reflects reference area levels. Comply with 1004 Rules

CA Resolution: Operator has addressed vegetation issues in order to comply with Rule 1004.