

Inspection Photos

API:061-06003

Operator: WHITING OIL & GAS CORPORATION

Inspection Date: 7/15/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the former access road. There are areas of the road that are bare of vegetation and areas that were not recontoured.



Inspection Photos



Photo 2. Facing southwest at the location. This area is bare of vegetation and there is an area of impacted material shown at red arrow and on the next photo.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06003 | Date: 7/15/2025

Inspection Photos



Photo 3. View of impacted oil stained soil.



Inspection Photos



Photo 4. There is a pipe riser/gas meter on location that was never removed.



Inspection Photos



Photo 5. Facing east at the location This area of bare soil is approximately 40 ft x 3 ft. wide.

