

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2025

Submitted Date:

07/18/2025

Document Number:

715202667

FIELD INSPECTION FORM

Loc ID 321689 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207793	WELL	TA	03/01/2024	OW	017-06728	ARAPAHOE UNIT 121(23-32)	TA

General Comment:

Location

Lease Road:

Type	Access		
comment:	Trail through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 207793 Type: WELL API Number: 017-06728 Status: TA Insp. Status: TA

Cement

Cement Contractor

Contractor Name: Franks Well

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2330/2060

Cement Volume (sx): 110SXS

Good Return During Job: _____

Cement Type: Class A w/4% gel

Comment: HALDE WATER, CODELL WELL SERVICE, FRANKS WELL SERVICE. MIRU CODELL, RIH W/CICR TO 2330'. MIRU FRANKS, PUMP 30 SXS THRU CICR W/5 SXS ON TOP. MIRU CODELL, LAY DOWN AND STAND BACK TBG. RIH W/CICR TO 2060'. MIRU FRANKS, PUMP 70 SXS THRU CICR W/5 SXS ON TOP. MIRU CODELL, LAY DOWN AND STAND BACK TBG. RIH W/CICR TO 1530'. INSPECTOR DEPARTED LOCATION AT 11AM.

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202672	workover rig and water trucks	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7149285