

Final Reclamation and Stormwater Inspection

July 15, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 335620

Location Name: GRENEMEYER-61N67W/26SESW

Inspection Document #: 718600779

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name:
GRENEMEYER-61N67W/26SESW
Location ID: 335620



Photo 1. Looking east down the former access road. The location and access road are within a fallow field.



Photo 2. Looking southeast across the wellbore area. No oil and gas equipment remains.



Inspection Photos
Location Name:
GRENEMEYER-61N67W/26SESW
Location ID: 335620



Photo 3. Looking east across the wellbore area. The location is within a fallow field. Vegetation on location is primarily undesirable weedy vegetation such as kochia.



Photo 4. Looking north from the wellbore location. See photo 3 comments.



Inspection Photos
Location Name:
GRENEMEYER-61N67W/26SESW
Location ID: 335620



Photo 5. Looking west from the wellbore location. See photo 3 comments.



Photo 6. Looking south from the wellbore location. See photo 3 comments.



Inspection Photos
Location Name:
GRENEMEYER-61N67W/26SESW
Location ID: 335620



Photo 7. Reference vegetation the the west of the well location. Reference vegetation is primarily undesirable weed kochia.