

Inspection Photos
Location Name: Conrad Federal 44-31 4N45W
API Number: 125-10650



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Conrad Federal 44-31 4N45W
API Number: 125-10650



3. Gas Meter inside Meter Shed.



4. View of produced water tank.

Inspection Photos
Location Name: Conrad Federal 44-31 4N45W
API Number: 125-10650



5. Produced water tank label is unreadable.



6. Disconnected tank and pump at well location with stained soil around bottom of tank.

Inspection Photos
Location Name: Conrad Federal 44-31 4N45W
API Number: 125-10650



7. Erosion on access trail looking up the grade to well location.



8. Erosion on access trail looking down from well location.

Inspection Photos
Location Name: Conrad Federal 44-31 4N45W
API Number: 125-10650



9. Closer view of erosion along access trail.



10. Erosion at edge of location looking down grade.

Inspection Photos
Location Name: Conrad Federal 44-31 4N45W
API Number: 125-10650



11. View of erosion channel as it continues down grade.



12. View of erosion channel as it continues down grade towards access trail.