




**RAT Observation**

- No Observed Source Material (4)
- Possible Source Material (0)
- Source Material Observed (0)





T137-1 RES - CONNELL JOHN - 23465 CR 72 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 548647 | 5/14/2025 12:30:18 PM  
(40.508079, -104.612706)  
Meter box on north east side of property





T137-1 RES - CONNELL JOHN - 23465 CR 72 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 548669 | 5/14/2025 1:13:07 PM  
(40.508303, -104.61245)  
East side of secondary residence facing well





**T137-1 RES - CONNELL JOHN - 23465 CR 72 WELD**  
**Photo Log | Rapid Assessment Technique (RAT)**

**Incident** Bishop LOC  
**Incident Date** April 7, 2025  
**City** Galeton, CO  
**County** Weld

Oiling Observation: 0 No Observable Oil | Id: 548687 | 5/14/2025 1:18:37 PM  
(40.508328, -104.612522)  
West side of residence



Oiling Observation: 0 No Observable Oil | Id: 548688 | 5/14/2025 1:27:25 PM  
(40.508049, -104.612879)  
Patio furniture set on East side of property

