

# Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328318

Inspection Document #: 718800529

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CANNON #H 35-09  
Location ID: 328318



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: CANNON #H 35-09  
Location ID: 328318



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: CANNON #H 35-09  
Location ID: 328318



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates bare ground and weedy annual vegetation, including russian thistle (*Salsola tragus*).



**Photo 6.** Photo taken of the access road to the well location, facing south. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and the site is dominated by russian thistle (*Salsola tragus*).

Inspection Photos  
Location Name: CANNON #H 35-09  
Location ID: 328318



**Photo 7.** Photo taken of the reference area to the well location, northwest of the location, facing west. Photo illustrates the site is dominated by sand sagebrush (*Artemisia filifolia*), prairie sunflower (*Helianthus petiolaris*), and thistle poppy (*Argemone polyanthemus*).

