

Inspection Photos
Location Name: P. Brophy 34-29 4N46W
API Number: 125-10055



1. Lease sign at well location.



2. View of wellhead. Note no Bradenhead visible at surface.

Inspection Photos
Location Name: P. Brophy 34-29 4N46W
API Number: 125-10055



3. View of wellhead. Note no Bradenhead visible at surface.



4. View of black poly line that appears to be three phase power at wellhead.

Inspection Photos
Location Name: P. Brophy 34-29 4N46W
API Number: 125-10055



5. Well location overview.



6. Lease sign at gathering location.

Inspection Photos
Location Name: P. Brophy 34-29 4N46W
API Number: 125-10055



7. Gas meter inside shared meter shed.



8. Shared gathering location overview.